

POWERUP LAWN CARE PRODUCTS

Proud Distributor of:



A Division of Roy Gripske & Sons Pty Ltd

11 Sodium Street, Narangba Qld 4504 PO Box 603, Redcliffe Qld 4020

Ph: (07) 3385 4955 or 1300 363 027 Fax: (07) 3385 4950 or 1800 33 22 13

Email: powerup@rgs.com.au Web: www.poweruplawn care.com.au

Product	ULTRA CUT CHAIN & BAR
Use	For chain saws and open chain drive chains
Ingredients	Refined mineral and chemical additives – determined to be non hazardous
Physical Data	
Density @ 15°C	0.886
Flash Point (°C)	Typical >230
Viscosity cSt @ 40°C	85
Fire & Explosion Hazard Data	
	Flash point over 170°C. Will not burn unless heated to high temperatures. Extinguish fires with CO ₂ , Dry Chemical, Foam or BCF. Fire Fighters should wear self-contained breathing apparatus if fire is in a poorly ventilated area and is too large for hand-held extinguishers
Health Hazard Data	
Eye Contact:	May cause mild irritation
Skin Contact:	May cause mild irritation
Inhalation:	May cause mild throat and nose irritation if inhaled at elevated temperatures
Swallowed:	May cause mild gastric irritation
Emergency & First Aid Procedures	
Eye Contact:	Flush with water for 15-20 minutes
Skin Contact:	Wash with soap & water
Inhalation:	Remove to fresh air
Swallowed:	DO NOT induce vomiting
IN ALL CASES SEEK MEDICAL ATTENTION IF DISCOMFORT PERSISTS	
Reactivity Data	
Product is considered stable under normal use conditions	
Incompatibilities:	Strong oxidisers Hazardous decomposition product
Spill or Leak Procedure	
Contain spill and shut off all sources of possible ignition Absorb on fire retardant material, sand or earth. Follow State or Local Authority regulations for disposal	
Storage & Handling Procedure	
Not defined as Dangerous Goods for transport by road or rail. Store away from heat, oxidising agents, food stuffs and clothing, No health risks are expected as a result of normal handling.	
For Information Contact	MARQUE LUBRICANTS Cnr Boundary Rd & Potassium St NARANGBA QLD 4504 Phone: (07) 3204 1844 Fax: (07) 3204 1855
Where the information provided in this bulletin indicates a potential hazard, adequate warning should be given to all employees or users and appropriate precautions taken, including the practices of good industrial hygiene.	